



SONOALTI 3V - SERVICE BULLETIN - MAY 2, 2024

Issue date: May 2, 2024

Bulletin number: FDSSB1

Identification: SonoAlti 3V units with firmware 1.0 or 1.1 (press the reset button adjacent the speaker with a paper clip to listen to the firmware number)

Compliance: HIGHLY RECOMMENDED for longevity and dependability of SonoAlti 3V

Background: Freefall Data Systems LLC has become aware of a number of units with failing speakers that can be remedied via a firmware and optional sound file update.

Action to be taken: Perform a firmware update or, optionally, replace the original sound files with improved files and then perform a firmware update. The sound file update is recommended and is for those wishing to retain or even enhance the volume of their unit. See freefalldatasystems.com/sonoalti_3v_firmware for all necessary files and instructions. FDS can carry out the update for any customers who send in their altimeter to the address below (please include a return address to send the updated unit in this case). When possible, altimeters will go back out on the same day they are received.

Authority: Casey Mongoven

Freefall Data Systems LLC
3710 Rucker Rd
Lompoc CA 93436

casey@freefalldatasystems.com